Maryland Historical Trust

The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001.

Maryland Inventory of Historic Properties number:

and .

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

MHT Number HO-662

Name and SHA No. Hipsley Mill Road over Cabin Branch/HO35
Location: Street/Road Name and Number: Hipsley Mill Road
City/Town: Annapolis Rock Vicinity x
County: Howard
Ownership:State_x_CountyMunicipalOther
This bridge projects over:RoadRailway_x_WaterLand
Is the bridge located within a designated district:yes_x_no
NR listed districtNR determined eligible districtlocally designatedother Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
Stone Arch
Metal Truss
Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical LiftRetractilePontoon
x Metal Girder x Rolled GirderRolled Girder Concrete EncasedPlate GirderPlate Girder Concrete Encased
Metal Suspension

HO-662

Metal Arch
Metal Cantilever
ConcreteConcrete ArchConcrete SlabConcrete BeamRigid FrameOther Type Name
Description:
Describe Setting:Bridge HO35 carries Hipsley Mill Road over Cabin Branch in Howard County, Maryland. Hipsley Mill Road runs in a generally north-south direction at this location; Cabin Branch runs generally north-south. The bridge is located just inside the northern boundary of Patuxent River State Park. The land for this park was purchased in the early 1960's and the park was established to be an undeveloped state park used for hunting and fishing. There are no public recreational facilities in the park. There is one late 19th-early 20th century domestic structure visible from the bridge.
Describe Superstructure and Substructure: The superstructure of Bridge HO35 is a single span steel beam bridge, with a corrugated metal deck and bituminous overlay on the roadway. There are W-beam guard rails on both sides of the bridge deck and along the northeast and southwest approaches. The span length is approximately 25', with a total bridge length of approximately 30'. The substructure is stone masonry abutments and wing walls.
Discuss Major Alterations: The county bridge inspection reports give no indication that any major alterations have been made to HO35.
History: When Built:1935 Why Built:local transportation needs Who Built:State Roads Commission Why Altered:n/a Was this bridge built as part of an organized bridge building campaign:yes Surveyor Analysis:
Surveyor Analysis:

Was this bridge constructed in response to significant events in Maryland or local history: HO35 was not constructed in response to significant events in Maryland or local history. It is merely a typical example of bridge construction in the early 20th century.

This bridge may have NR significance for association with:

_A Events _B Person

__C Engineering/Architectural

HO-662

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area: No, construction and/or alteration of HO 35 did not have a major impact on the growth and development of the area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district:No, this bridge is not located in an area which may be eligible for historic designation.

Is the bridge a significant example of its type: While HO35 does retain many of its original structural elements, it is not a significant example of a steel beam bridge.

Does the bridge retain integrity of the important elements described in the Context Addendum:Rolled wide flange beams are considered primary character defining elements. According to the 1995 inspection report they are in fair condition and have never been repaired or replaced. The same can be said for the floor system and the corrugated metal bridge deck, which are both considered secondary character defining elements. The inspection report recommends cleaning of debris and rust from the beams and repainting. W beam guard rails are considered tertiary character defining elements as additional functional features. The guard rails for HO35 have been replaced several times in the past years, most recently in 1989.

Stone masonry abutments and wing walls are considered a primary character defining element. While there is no documentary evidence that the abutments have been altered, it is obvious by looking at them that there has been an attempt to repair them by applying concrete. Even with this repair work they are still in poor condition, as indicated by the 1995 county inspection report. The report recommends immediate repair work to the abutments to prevent further deterioration.

While the superstructure of HO35 is in satisfactory condition, the severe state of disrepair of the abutments and wing walls places the integrity of the structure in doubt.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer and why:No, HO35 is not a significant example of the work of a manufacturer, designer and/or engineer.

Should this bridge be given further study before significance analysis is made and why: No, this bridge should no be given further study before significance analysis is made.

40-662

Bibliography:

Howard County

Bridge Inspection Files. v.d

Greiner, Inc.

1995 Historic Bridge Inventory Form.

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context.


1

United States Geological Survey

1945 7.5' Woodbine Quadrangle, photorevised 1979.

Surveyor:

Name: Stephanie L. Bandy Date: August 1995
Organization: State Highway Admin, Telephone: (410) 321-2213
Address: 2323 West Joppa Road Brooklandville, MD 21022





Inventory	#	Ha	agent .	6	6	2

Name HO35-HIPSLEY MILL RD OVER BRANCH
County/State HOWARD MD
Name of Photographer DAVID DIEHL
Date 2 95
Location of Negative SHA
Doublet of Hogazia
Description South Approach Looking
PORTHEAST
Number 13 of 2



Inventory # Ho-le(e2
Name HO35 - RIPSLEY MILL ROOVER CABIN BRANCH
County/State HOWARD MP
Name of Photographer DAVID OIE HL
Date 2 95
Location of Negative SHR
200
Description NORTH APPROACH LOOKING

Number 19 of 3

SOUTHWEST



Inventory # Ho-662
Name HO35 - HIPSLEY MILL RD OVER (ABIN BRANC County/State HOWARD M)
Name of Photographer ORVID DIENL
Date 2 95
Location of Negative SHR
Description EAST ELEVATION LOOKING
NORTH
3 1
Number 15 of 21

A STANK



Inventory # <u>H0-662</u>

Name HO35-HIPSLEY MILL RO OVER (ABIN BRANCH County/State AOWARD IMD
Name of Photographer DAVID DIENL
Date 2 95
Location of Negative SHR
Description WEST ELEVATION LOOKING
EAST
4
Number of 3

INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: <u>Hipsley Mill Road over Cabin Branch</u> Survey Number: HO-662 Project: Bridge replacement Agency: HO DPW Site visit by MHT Staff: X no yes Name Date Eligibility recommended ____ Eligibility not recommended XX Justification for decision: (Use continuation sheet if necessary and attach map) Based on the available information, the Hipsley Mill Road Bridge over Cabin Branch, Howard County is a 1935 rolled metal girder bridge. It is missing its original deck which was replaced in 1960, and the parapets were removed at an earlier unknown date. Steel guardrails replaced an earlier set in 1989. The girders have poor integrity, displaying heavy rust. The two abutments upon which the bridge sits have also been frequently patched in the past. Based on this information, the Hispley Mill Road Bridge is not eligible for the National Register of Historic Places. It lacks the requisite integrity necessary for consideration of eligibility. Documentation on the property/district is presented in: Project Review and Compliance Prepared by: Paula Spero & Company and Howard County Dept. of Public Works Anne E. Bruder 2/20/98 Reviewer, Office of Preservation Services Date NR program concurrence: X yes ___ no ___ not applicable Reviewer, NR program Date

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

1.	Geographic Region:	
	Eastern Shore	(all Eastern Shore counties, and Cecil)
	Western Shore	(Anne Arundel, Calvert, Charles, Prince George's and St. Mary's)
X	Piedmont	(Baltimore City, Baltimore, Carroll,
		Frederick, Harford, Howard, Montgomery)
	_ Western Maryland	(Allegany, Garrett and Washington)
II.	Chronological/Developmental	Periods:
	Paleo-Indian	10000-7500 B.C.
	_ Faico-indian _ Early Archaic	7500-6000 B.C.
	Middle Archaic	6000-4000 B.C.
	Late Archaic	4000-2000 B.C.
	Early Woodland	2000-500 B.C.
	Middle Woodland	500 B.C A.D. 900
	Late Woodland/Archaic	A.D. 900-1600
-	Contact and Settlement	A.D. 1570-1750
	_ Rural Agrarian Intensification	A.D. 1680-1815
	Agricultural-Industrial Transition	A.D. 1815-1870
	Industrial/Urban Dominance	A.D. 1870-1930
$\overline{\mathbf{x}}$	-	A.D. 1930-Present
	Unknown Period (prehistor	
III.	Prehistoric Period Themes:	IV. Historic Period Themes:
	Subsistence	Agriculture
	_ Settlement	XX Architecture, Landscape Architecture,
	n 11/2 1	and Community Planning
	_ Political	Economic (Commercial and Industrial)
	_ Demographic	Government/Law
	_ Religion	Military
	_ Technology	Religion Social/Educational/Cultural
	_ Environmental Adaptation	XX Transportation
V. F	Resource Type:	
	Category:Str	ucture
		ural
	Historic Function(s) and Use(s)	Bridge/Transportation
	Known Design Source:	

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/ MARYLAND HISTORICAL TRUST

MHT No. <u>HO-662</u>

SHA Bridge	No. <u>HO 035</u>	Bridge nameH	lipsley Mill Road	Bridge over Ca	bin Branch
LOCATION Street/Road		per [facility carried]	Hipsley Mill	Road	
City/town _	Hipsley Mill			Vicinity	
County	Howard		,		
This bridge	projects over: R	Road Railwa	v v	Vater X	Land
Ownership:	State	_ County <u>X</u>	Municipa	al Ot	her
Natio	e located within onal Register-lis	a designated histor ted district istrict	National Registe	er-determined-el	igible district
Name of dis	trict				
Stone Arch	lge:		I Trestle	Timber-A	nd-Concrete
Movable Bri Swin		Bascule Si	ingle Leaf		ple Leaf
	er X : ed Girder X e Girder		der Concrete Enca er Concrete Enca		_ _
Metal Suspe	ension	-			
Metal Arch					
Metal Canti	lever				
	rete Arch	Concrete Slab_ pe Name	Concrete I		id Frame

DESCRIPTION:			
Setting: Urban	Small town	Rural	<u>X</u>

Describe Setting:

Bridge HO 035 carries Hipsley Mill Road over Cabin Branch in Howard County. Hipsley Mill Road runs northeast-southwest and Cabin Branch flows northwest-southeast. The bridge is located at Hipsley Mill, and is surrounded by woodland and one (1) residence. The bridge is located in the Patuxent River State Park, approximately 30.48 meters (100 feet) north of the intersection of Hipsley Mill Road and Annapolis Rock Road.

Describe Superstructure and Substructure:

Bridge HO 035 is a single-span, two-lane, metal girder bridge constructed in 1935. The original deck and road surfaces were replaced circa 1960 and the bridge railings were replaced by guardrails at an unknown date. The guardrails were replaced again in 1989 with steel guardrails. The structure is 8.69 meters (28.5 feet) long and has a clear roadway width of 5.89 meters (19.3 feet); there are no sidewalks. The out-to-out width is 6.1 meters (20 feet). The bridge was built on a 14° skew. The superstructure consists of ten (10) rolled girders which support a corrugated metal and concrete deck and steel guardrails. The girders are 139.7 millimeters (5.5 inches) wide x 381 millimeters (15 inches) deep and are spaced an average of 0.62 meters (2.05 feet) apart. The roadway is carried on the girders. The corrugated metal and concrete deck is 114 millimeters (4.5 inches) thick and it has a bituminous wearing surface. The structure has steel guardrails and the roadway approaches have steel guardrails and no shoulders. The substructure consists of two (2) stone abutments that have areas of gunite patches and stone and concrete riprap. There are four (4) flared stone wing walls with gunite caps. The southwest wing wall has been partially covered with asphalt. The bridge is posted for 18.74 tonnes (17 tons) and 48 kilometers per hour (30 miles per hour), and has a sufficiency rating of 25.9%.

According to the 1997 inspection report, this structure was in poor condition with rusting on the girders and a large pothole on the deck. The asphalt wearing surface is uneven with some cracking, and the pothole has been covered with a steel plate. The girders have moderate rust, and the corrugated metal deck is heavily rusted. There is dirt and debris accumulating on the beam seats. The stone masonry abutments and wingwalls have been patched with gunite and asphalt, which is deteriorating in areas. The exposed masonry exhibits moderate mortar loss.

Discuss Major Alterations:

LICTODV.

Other (specify):

The original deck and road surfaces were replaced circa 1960 with a new corrugated metal and concrete deck. Gunite was applied to the abutments and wing walls in 1981-1982, and a large pothole on the deck was covered with a steel plate in 1997. The original railings were first replaced with guardrails at an unknown date. The current guardrails date to 1989.

IIISTOKI:			
WHEN was the bridge built: _	1935		
This date is: Actual	X	Estimated	
Source of date: Plaque	Design plans	County bridge files/inspection form	X

WHY was the bridge built?

The bridge was constructed in response to the need for more efficient transportation network and increased load capacity.

WHO was the designer?

Unknown

WHO was the builder?

Unknown

WHY was the bridge altered?

The bridge was altered to correct functional or structural deficiencies.

Was this bridge built as part of an organized bridge-building campaign?

Unknown

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have N	lational Register significanc	ce for its association with:
A - Events	B- Person	
C- Engineering/a	architectural character	

Bridge HO 035, Hipsley Mill Road Bridge, was determined eligible for the National Register of Historic Places by the Interagency Review Committee in 1996. P.A.C. Spero & Company requests that the National Register eligibility of this structure be reconsidered. The bridge is recommended as not eligible for the National Register. A significant example of a metal girder bridge should possess character-defining elements of its type, and be readily recognizable as an historic structure from the perspective of the traveler. The integrity of distinctive features visible from the roadway approach, including railings, is important in structures such as bridge HO 035, which are common examples of their type. The railing of the structure has been replaced. The new railing is a steel guardrail which extends across the bridge and along the roadway approaches. The structure also lacks the integrity of its character-defining elements.

The revised 1995 <u>Historic Highway Bridges in Maryland</u>: 1631-1960 describes the history and structural components of each type of bridge within Maryland. The components or members needed for assessing historic integrity are known as character defining elements (CDE's). The alteration, elimination, and present condition of CDE's should be taken into account when determining a structure's integrity. Bridge HO 035 is a rolled metal girder bridge and according to <u>Appendix C</u> in the <u>Historic Highway Bridges in Maryland:1631-1960</u> a rolled metal girder bridge has three primary CDE's. The primary CDE's for a rolled metal girder bridge include rolled longitudinal I-beams, abutments of stone concrete or timber and a pier, if applicable. Bridge HO 035 possesses two character-defining elements; the rolled girders and stone abutments. The historic integrity of the structure has been compromised by the condition and alteration of these elements. The rolled metal girders are in poor condition, with heavy rusting and section loss of the bearing plates and fascia beams. The interior beams have moderate section loss and rusting. The stone masonry abutments and wingwalls have minor mortar loss. The masonry has been coated with gunite from a repair in 1981-1982, which is cracking, and the southwest wingwall has been covered with asphalt.

Therefore, bridge HO 035 is recommended as not eligible of the National Register of Historic Places.

Was the bridge constructed in response to significant events in Maryland or local history?

Metal girder bridges were most likely introduced and first popularized in Maryland by the state's major railroads of the nineteenth century including the Baltimore and Susquehanna, its successor the Northern Central, and the Baltimore and Ohio Railroad. Bridge engineering historians have documented the fact that James Milholland (or Mulholland) erected the earliest plate girder span in the United States on the Baltimore and Susquehanna Railroad in 1846 at Bolton Station, near present-day Mount Royal Station. The sides (web) and bottom flange of Milholland's 54-foot-long span were wholly of wrought iron and included a top flange reinforced with a 12x12-inch timber. Plates employed in the bridge were 6 feet deep and 38 inches wide, giving the entire bridge a total weight of some 14 tons. Milholland's pioneering plate girder cost \$2,200 (Tyrrell 1911:195). By December 31, 1861, the Northern Central Railroad, which succeeded the Baltimore and Susquehanna, maintained an operating inventory in Maryland of 50 or more bridges described simply as "girder" spans, in addition to a number of Howe trusses. Most of these were probably iron girder bridges; the longest were the 117-foot double-span bridge over Jones Falls and the 106-foot double-span girder bridge at Pierce's Mill (Gunnarson 1990:179-180).

As in the nation, girder bridge technology in Maryland was quickly adapted to cope with the increasingly heavy traffic demands of the twentieth century caused by automobile and truck traffic. The 1899 Maryland Geological Survey report on highways noted that "there are comparatively few I-beam bridges, one of the cheapest and best forms for spans less than 25 or 30 feet" (Johnson 1899:206). Interestingly, the report also urged construction of a composite metal, brick, and concrete bridge, noting that "no method of construction is more durable than the combination of masonry and I-beams, between which are transverse arches of brick, the whole covered with concrete, over which is laid the roadway" (Johnson 1899:206). Whether any such bridges (transitional structures between I-beams and reinforced concrete spans) were built is unknown.

Official state and county highway reports—issued between 1900 and the early 1920s through the Highway Division of the Maryland Geological Survey and its successor, the State Roads Commission, generally do not reference or describe girder construction. An analysis of the current statewide listing of county and municipal bridges (a listing maintained by the State Highway Administration) reveals that 48 county bridges, out of the total of 141 approximately dated to "1900" by county engineers, were listed as steel girder, steel stringer, or variants of such terms. (It should be noted that the "1900" date is often given when no exact date is pinpointed for a bridge that is clearly old). A grand total of 200 bridges (including "steel culverts"), out of 550 bridges dated on the county list between 1901 and 1930, were described as steel beam, steel girder, or steel stringer and girder varieties. The total suggests that among the various highway bridge types built in the early twentieth century metal girder bridges in Maryland between 1900 and 1930 were second in popularity only to reinforced concrete bridges. However, these numbers must be interpreted with caution, as they do not necessarily include all county and municipal bridges.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

Is the bridge a significant example of its type?

Phone number(410) 296-1635

The bridge is an undistinguished example of a metal girder bridge which lacks integrity of its character-defining elements.

Does the bridge retain integrity of important elements described in Context Addendum?

The bridge does not retain integrity of the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including the rolled metal girders and stone abutments.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?


This bridge is not a significant example of the work of a manufacturer, designer, and/or engineer.


Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.


BIBLIOGRAPHY:
County inspection/bridge files SHA inspection/bridge files Other (list):
Gunnarson, Robert 1990 The Story of the Northern Central Railway, From Baltimore to Lake Ontario. Greenberg Publishing Co., Sykesville, Maryland.
Johnson, Arthur Newhall 1899 The Present Condition of Maryland Highways. Report on the Highways of Maryland. Maryland Geological Survey, The Johns Hopkins University Press, Baltimore.
Tyrrell, Henry G. 1911 History of Bridge Engineering. Published by author, Chicago.
SURVEYOR:
Date bridge recordedNovember 1997
Name of surveyor Caroline Hall/Ryan McKay
Organization/Address P.A.C. Spero & Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204

FAX number (410) 296-1670











TO KIM



2 M. M. ET HALL

